BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0215, W0224	NA	GANESHA TEMPLE OPPOSITE
Segment No.	**Total Length (m)**	
13/C-W0215/S045320	117.42	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	117.42	77.517226	13.049475	77.517660	13.050445	PIPELINE	GANESHA TEMPLE OPPOSITE

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
PROVIDING CEMENT CONCRETE TO MAIN ROADS OF SANTOSHNAGARA	980000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	RCC DRAIN
Tender	**Work Details**	**Job No. / Work Code**
Tender		013-12-000027
Work Order No.	**Work Order Date**	**Period of Extention**
EE\DD\WO\155\13-14	14/11/2013	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B UMESH		0.00
Phone No.	**E-Mail ID**	
8723642838		

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Field Inspection Details

Number of Trees	Any Other Information	Name
0		nagabhushan

Date of Inspection	Remarks
22/08/2015	

Category	Image	Photo Remark
Drain Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDDEGOWDA	22/08/2015	31/08/2015	COMPLETED
EE	JOGISIDDEGOWDA	22/08/2015	31/08/2015	COMPLETED
AEE	JAYALINGAPPA	22/08/2015	31/08/2015	COMPLETED
AE	NAGABHUSHAN	22/08/2015	31/08/2015	COMPLETED
AE	NAGABHUSHAN	22/08/2015	14/08/2015	COMPLETED

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು